



IMPORTANT

Read through all the steps before starting procedure. Please refer to the appropriate MSDS for proper safe handling including the use of safety glasses, protective gloves, and respirator protection where needed. For any reason if you do not understand, or are uncertain of any or all procedures and instructions given to you by Foam Supplies, Inc. and its representatives please contact our Technical Dept. first, before attempting procedures. We will be happy to assist.

PROTECTIVE EYEWEAR AND GLOVES REQUIRED!

SPILLS/LEAKS: Refer to MSDS.

1. Evacuate and ventilate spill area. Notify appropriate personnel.
2. Wear appropriate protective equipment during clean up. See MSDS.
3. Dike spill to prevent entry into water or sewage system.
4. May present a slipping hazard.

MAJOR SPILL:

1. Call Foam Supplies, Inc. at 1.314.344.3330
2. For spills in transit, call **CHEMTREC:**
Inside USA 1.800.424.9300
Outside USA 1.703.527.3887
3. Dike chemical and divert flow if possible. Large quantities should be pumped into closed containers for disposal.
4. See Minor Spill for clean up procedure.

MINOR SPILL:

1. Absorb with dry sawdust, floor-dry, sand, clay soil, or other suitable absorbent material.
2. Remove and store in containers. Label as required.

DISPOSAL METHOD:

1. Follow all Federal, State and Local regulations.
2. Contact a licensed hazardous waste disposal contractor for proper disposal.
3. Obtain certification and receipts of proper disposal from contractor.